



Electric Heater Lead Welding Instructions

Gas Weld

1. Place coil end parallel to the rod and tie the coil lead to the rod with nichrome wire to hold the lead in place while welding. (See Figure 1).




2. To weld the coil to the rod, use an oxyacetylene flame. For filler rod, use excess heater coil wire. Use a soft flame to melt filler rod and fill in around coil leads to form a "ball". Do not try to weld the coil leads directly to the rod. No flux is required. (See Figure 2).



CAUTION: Too hot a flame or applying too much heat to the coil leads can burn them off or cause crystallizing. Keep flame moving.

3. When the coil leads have been built up by the application of filler rod, increase flame heat. Apply the flame to the rod and add filler between the rod and built-up leads, gradually fusing them together. (See Figure 3).



TIG Weld

Joint

Type of Welded Joint: J-Groove
Backing Material: No

Gas

Shielding Gas: Argon
Percent Mixture: 100% Argon
Flow Rate: 10-14 CFH

Base Metal

Sheet steel to SS Rod (support steel)

Coating

Type: None

Filler Metal

Specification: If required, chromel lead wire
Classification: Same as heater lead

Preheat

Preheat Temperature Min: None

Technique

Pass No.	Tungsten Size	Welding Current		Travel Speed
		Amperes	Volts	
1	with 3/8" nozzle .062 diameter	60-78 60 nom.	17-19	N/A

1. Start puddle.
2. Before melting wire use a slight weave.
3. Once you start melting wire, lead the puddle with torch.




FIGURE 4